

SAFETY AND SECURITY INFORMATION

IN CASE OF EMERGENCY CALL

+36 20 937 4210

- Entry only with registration and entry permit
- It is forbidden to enter under the influence of alcohol or drugs!
- It is prohibited to bring sharp objects, cutting tools and firearms!*
- Visitors may stay in the power plant only with their escort.**
- Work can be performed only after completing the introductory safety training and having a valid written permit for work.
- Smoking is only allowed in designated areas!
- Pay attention to vehicle traffic and give them a clear path!
- Keep a safe distance from suspended loads!
- Do not look directly at the welding arc!
- First aid points are marked with a white cross on a green background.
- In case of fire, remain calm do not use elevators and call the number above.
- In case of evacuation, go immediately to the assembly point at Gate no. II, wait for the personnel check, do not leave the power plant.

* except for the tools needed for work

** except for the walkway between Gate no. II and Building "C"

SIGNS

PPE's



Prohibitions



Informations



